

Date	Location	Complaints	By
8/10/2021	Ground Floor A9 - A10 - A8 - A-12 -	1 - New tubelight - 1 pipe leakage 2 Fan - No speed 3 tubelight Not working, 5 Fan No speed	By
15/11/2021	Third Floor. (Pharmacology). D ₁ - D ₄ , D ₈ -	Corridor door window panel - 1 pane missing. Tubelight not working. Flush repair. Flush repair.	Emily James
23/11/2021	Second floor	Central instrument room inlet connection	Rax
29/12/2021	1 st Floor Library	photocopy machine not working.	
31/12/2021	3 rd Floor	Windows - 4, Switch - 1, socket - 2 Corridor glass - 1, lock - 1	Suy
31/12/2021	2 nd Floor	False ceiling, current fluctuations Tubelight (3) Fan - (2), Common Room door, curtain, cooler Plug socket (2)	Am
31/12/2021	4 th floor	310k leakage - 5 no. New Switch Board 9 no. (P.G. lab * Ph. cognosy, Ph. chemistry) switch board damage - 1 no. (P.G. lab pharmacology) Water cooler complaint Door lock Room no: 12 Door complaint Room no: 24 E7 (preparation room) New tubelight	

GPS Map Camera



Thiruvalla, Kerala, India

CH64+R98, Pushpagiri Medicity Road, Thiruvalla, Kerala

686548, India

Lat N 9° 24' 39.2544"

Long E 76° 33' 23.364"

18/11/22 02:06 PM GMT +05:30



Seen By	Work Executed	Remarks
04/10/21	Ground floor Dining room (Bath doors light not working)	Shree
5/10/21	11 th floor Electrical socket not working	Raghu
7/10/21	11 th floor Escalator light, fan not working, windows and condenser lock not working.	Sujatha P Dhath
12/10	11 th floor electrical socket need to change	Raghu
13/10/2021	First floor Faculty room - Phone complaint - Common room - Pipe, water not coming	Dhath
27/10	Instrumentation room	R
10/11/2021	Photocopy machine is not working.	R
12/11/21	1 st floor Lab - oven plug Common room - door Bathroom door Wash basin	R

GPS Map Camera




Thiruvalla, Kerala, India
 CH64+R98, Pushpagiri Medicity Road, Thiruvalla, Kerala
 686548, India
 Lat N 9° 24' 39.2544"
 Long E 76° 33' 23.364"
 18/11/22 02:06 PM GMT +05:30



MAINTANENCE AND REPAIR REQUEST FORM

GPS Map Camera

Thiruvalla, കേര, India
 CH64+R98, Pushpagiri Medicity Road, Thiruvalla, കേര
 686548, India
 Lat N 9° 24' 39.258"
 Long E 76° 33' 23.3712"
 18/11/22 02:07 PM GMT +05:30



PUSHPAGIRI COLLEGE OF PHARMACY MAINTENANCE AND REPAIR REQUEST FORM			
DATE	4/11/22	TIME	10:30 AM
FLOOR & DEPT	3 rd Floor, Pharm-D Block		
ROOM ID			
COMPLAINT			
Light not working (Passage) Bathroom door lock complaint (Cegir's Common Room) Bathroom door lock complaint (Di Room) floor not working (Di Room) fan speed			
REPORTED BY	SUJATHA P.P.	DATE	4/11/22
RECEIVED BY	JOSH JAI	DATE	4/11/22
FORWARDED TO	Electrical department	DATE	4/11/2022
BUILDING/ELECTRICAL DEPARTMENT			
ASSESSMENT			ASSESSED BY
APPROVAL FOR WORK			
		SIGN	
COMPLETED BY			
SUPERVISED BY			
REMARKS			
Low Led tube set # 1 (res), Dh, Slush Tank Repair, 22 Fan Capacitor # 1 res 18/11/22			
SUPERVISOR - BUILDING/ELECTRICAL			SIGN
APPROVAL FOR PAYMENT (IF ANY)			
		SIGN	

PUSHPAGIRI
UNIVERSITY OF PHARMACY
REPAIR & MAINTENANCE REQUEST FORM

DATE	10/11/22	TIME	2.15 PM
FLOOR & DEPT	11 th , Pharmaceutical chemistry		
ROOM ID	C10		
COMPLAINT			
Fan not working			
REPORTED BY	Sane Paul	DATE	10/11/22
RECEIVED BY	JOBIN JOY <i>[Signature]</i>	DATE	10/11/22
FORWARDED TO	Electrical Department	DATE	10/11/22
BUILDING/ELECTRICAL DEPARTMENT			
ASSESSMENT		ASSESSED BY	
APPROVAL FOR WORK			
COMPLETED BY	<i>[Signature]</i>		
SUPERVISED BY			
6A Switch		REMARKS	3 nos
		cables Completed	
SUPERVISOR - BUILDING/ELECTRICAL	<i>[Signature]</i>		SIGN
APPROVAL FOR PAYMENT / TRANSFER			
		SIGN	

GPS Map Camera

Thiruvalla, കേരള, India
 CH64+R98, Pushpagiri Medicity Road, Thiruvalla, കേരള
 686548, India
 Lat N 9° 24' 39.2544"
 Long E 76° 33' 23.364"
 18/11/22 02:07 PM GMT +05:30

